























Assembly Instruction




Step 1










Step 2

				
P1	B2	B2	B2	B2
				
T1				
				
L3				
				
L4				
		$\Phi 1/4 \times 11 \times 1.5T$ 32 PCS	$\Phi 1/4 \times 11 \times 1.5T$ 32 PCS	4mm 1 PC
		$\Phi 1/4 \times 12 \times 1.5T$ 32 PCS	$\Phi 1/4 \times 12 \times 1.5T$ 32 PCS	
		$\Phi 1/4 \times 35mm$ 12 PCS	$\Phi 1/4 \times 35mm$ 12 PCS	
		$\Phi 1/4 \times 45mm$ 20 PCS	$\Phi 1/4 \times 45mm$ 20 PCS	

Assembly Instruction



Step 3

P1		$\phi 1/4 \times 11 \times 1.5T$ 32 PCS	B2		4mm 1 PC
T1		$\phi 1/4 \times 12 \times 1.5T$ 32 PCS			
L3		$\phi 1/4 \times 35mm$ 12 PCS			
L4		$\phi 1/4 \times 45mm$ 20 PCS	